Wednesday, 3/15/2006 3:42:27 PM Kim Johnston User: **Process Sheet** : BEARPAW KIT (19"X16") **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number : 26251 : 10320 **Estimate Number** Part Number : K10007 :NA P.O. Number : D2435 REV E1 **Drawing Number** : 3/15/2006 S.O. No. : N/A This Issue : N/A : NC Project Number Prsht Rev. : N/A : MACHINED PARTS : E1 **Drawing Revision** First Issue Type AIM: : 25289 Material **Previous Run** : 3/22/2006 10 Um: **Due Date** Qty: Written By Checked & Approved By Blank size changed KJ/JLM Comment **Additional Product** Job Number: Description: Machine Or Operation: Seq. #: DOCUMENT CONTROL 1.0 DC Comment: DOCUMENT CONTROL Photocopy bluefile: K10007 D206-559 D500-572 D120-638 D058-678 and create labels per PPP K10005 CHG003 06/04/01 (Bag Bluefiles separately) MUHMWB10 UHMW 1" Black 2.0 Comment: Qty.: 45.4913 sf(s) 4.5491 sf(s)/Unit Total : blank: 19.500" x 16.00" x 1.00" thick (+0.030/-0.000) per DSK086-3 Material: Black UHMW 1" (MUHMWB10) 06/04/01 Batch: M17726 HAAS CNC VERTICAL MACHINING #1 3.0 HAAS1

10

Each



Comment: HAAS CNC VERTICAL MACHINING #1

Note: (2) Bearpaw for (1) Kit

1-Inspect material for defects or damage prior to machining

2-Machine as per Folio and Dwg D2435 Identify as D2435

3-Deburr

gal 06/04/03

10

<b>W</b> /O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
· -					•.						
Part No	:	PAR #: Fault Category:	NCR: Ye	s No DQA	\:	_ Date: _					

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_

NCR:		V	VORK ORD	ER NON-CONFORM	ANCE (NCR)			
		Description of NC		Corrective Action Sect	Verification			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
				i				
							,	
						!		
NOTE: D	ate & initial a	all entries						

Wednesday, 3/15/2006 3:42:27 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: BEARPAW KIT (19"X16") Customer: CU-DAR001 Dart Helicopters Services Job Number: 26251 Part Number: K10007 Job Number: Seq. #: Description: Machine Or Operation: INSPECT PARTS AS THEY COME OFF MACHINE QC2 4.0 06/04/03 Comment: INSPECT PARTS AS THEY COME OFF MACHINE 10 SECOND CHECK QC8 5.0 10 Comment: SECOND CHECK PACKAGING RESOURCE #1 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Pick Packing Kit Neoprene Cushion-.750 bl 7.0 D2182B Comment: Qty.: 0.4160 f(s)/Unit Total: 4.1600 f(s) Pick: Packing Kit Qty Part Number Description Batch Rubber Cushion B34870 4 D2182B050 8.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 80.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch B25769 Radius Block 8 D2274 Bearpaw Babati 2 D2435(ref only) Clamp 9.0 D2438 4.0000 Each(s)/Unit Total: 40.0000 Each(s) Comment: Qty.: Pick: Packing Kit Qty Part Number Description Batch Clamp <u>D25015</u> 11ML4.
B28963B 3MC4 B2561126MQ. 4 D2438

<b>Dart Aerospace</b>	Ltd
-----------------------	-----

		<del></del>						
W/O:			WC	RK ORDER CHANG	ES			
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No:		PAR #:	Fault Cateç	ory:	NCR: Yes	No <b>DQA</b> :	_ Date: _	
						/C Closed:	_ Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR	()		
DATE	eten	Description of NC		Corrective Action Section		Verification	Approval	Approval
	SILF	Section A Initial	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
				1				
				: 				
				İ				
	,							
						-		
				!				
	1 1		1 1	1		i	1	1

Date: Wednesday, 3/15/2006 3:42:27 PM User: Kim Johnston **Process Sheet** Drawing Name: BEARPAW KIT (19"X16") Customer: CU-DAR001 Dart Helicopters Services Part Number: K10007 Job Number: 26251 Job Number: **Description:** Seq. #: Machine Or Operation: Washer 10.0 D2529 8.0000 Each(s)/Unit Total: 80.0000 Each(s) Comment: Qty.: Pick: Packing Kit Qty Part Number Description Batch 8 D2529 Washer 1525372 AN415A 11.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 80.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch Bolt AN4-15A AN417A 12.0 8.0000 Each(s)/Unit Total: 80.0000 Each(s) Comment: Qty.: Pick: Packing Kit Qty Part Number Description Batch 8 AN4-17A AN960JD416 Washer 13.0 Comment: Qty.: 16.0000 Each(s)/Unit Total: 160.0000 Each(s) Pick: Packing Kit 14.0 MS21042L4 Nut Comment: Qty.: 8.0000 Each(s)/Unit Total: 80.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch M19098 8 MS21042L4 🗸 Nut (or -4)

W/O:		WORK ORDI	ER CHANGES	ANGES				
DATE	STEP	PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		I						
	·							
		:						

Part No:	PAR #:	Fault Category:	NCR: Yes (No) DQA:	Date: <u>060465</u>
		1	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
D.4.T.F		Description of NC		Corrective Action Section E	3	Verification	Approval	Approval QC Inspector			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng				
				İ							
						;					
<del></del>											
				l							
								1			

Wednesday, 3/15/2006 3:42:27 PM Date; User: Kim Johnston **Process Sheet** Drawing Name: BEARPAW KIT (19"X16") Customer: CU-DAR001 Dart Helicopters Services Part Number: K10007 Job Number: 26251 Job Number: Seq. #: Description: **Machine Or Operation:** QS200M44S Clamp 15.0 Total: 20.0000 Each(s) 2.0000 Each(s)/Unit Comment: Qty.: Pick: Packing Kit Qty Part Number Description Batch Clamp <u>M19554</u> 2 QS200M44S Paperwork package QC4 INSPECT 100% KITS FOR COMPLETENESS 16.0 Comment: INSPECT 100% KITS FOR COMPLETENESS PACKAGING RESOURCE #1 PACKAGING 1 17.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPPk10007 C206/04/04 Location: DOCUMENT CONTROL 18.0 DC W D604/05 Comment: DOCUMENT CONTROL Inspection Level 21 Job Completion

Dart Ae	rospace	e Ltd		i				
W/O:			V	ORK ORDER CHANGES				
DATE	STEP	PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				i ! !				
				1				
			• .				• .	
Part No	•	PAR #:	Fault Cat	egory:N	CR: Yes 1	No DQA:	_ Date: _	
		•		1.	QA: N/	C Closed:	Date: _	
NCR:			WORK OR	DER NON-CONFORMANC	E (NCR)			
DATE	CTED	Description of NC		Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description  Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
-	T			<del></del>		+		

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section	В	Verification	Approval Chief Eng	Approval QC Inspector			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C					
				1							
				· 1							
				1							
				1 -							
				1							
				!							
						,					

DART AEROSPACE LTD	Work Order:	26251
Description: Bearpaw	Part Number:	D2435
Inspection Dwg: D2435 Rev: E1		Page 1 of 1


## FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

	pection Sheet ving Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Α	0.063 x 45°	+0.030/-0.010	0.057x45°				
В	5.500	+/-0.030	<b>5</b> .501				
С	0.200	+/-0.030	0.196				
D	R0.250	+/-0.030	R0.250				
E	0.250	+/-0.010	0.242	J			
F	0.625	+/-0.030	0.614				
G	0.25 x 45°	+/-0.030	0,240 X45			:	
Н	0.375	+/-0.010	0.385				
ı	19.000	+/-0.030	19.000	_			
J	0.950	+0.030/-0.010	6.956				
К	Ø0.260	+0.005/-0.000	\$0.260				
L	Ø0.930	+/-0.030	\$ 0.930				
М	0.30	+0.030/-0.000	0.305				
N	0.375	+/-0.030	0.385				
0	7.375	+/-0.030	7.375				
Р	4.250	+/-0.010	4.250				
Q	2.000	+/-0.030	2,000				
R	9.000	+/-0.010	9.000				
S	15.750	+/-0.030	15.750	_			

Measured by:	gal	Audited by:	Ep	Prototype Approval:	N/A
Date:	06/04/02	Date:	06/04/02	Date:	NIA

Rev	Date	Change		Revised by	Approved_
Α	03.09.22	New Issue	P/O K10007	KJ/RF →	4



Copyright 1996 by DART AEROSPACE LTD

SUBJECT TO AMENDMENT WITHOUT NOTICE


WORK ORDER NO. 26251


<b>W</b> /O:		WO	<b>ORDER CHANGES</b>					
DATE	STEP	PROCEDURE CHAN		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
4								
:								


Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
			QA: N/C Closed:	Data
			QA: N/C Closed:	Date:


NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
DATE		Description of NC		Corrective Action Section B					
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector	
				:					
				1					











SECTION C-C

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT

W:THOU! NO

WORK ORDER

<b>W</b> /O:			K ORDER CHANGES	-				
DATE	STEP	PROCEDURE C	SE .	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	*							
			·					

Part No:	PAR #:	_ Fault Category:	NCR: Yes No DQA:	Date:
			QA: N/C Closed:	Date:

NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
DATE		Description of NC		Corrective Action Section B			Verification Approval	Τ		
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
•										
						,				
						:				
	1 2 : :: 1			1				1		